

ANTER OUT OF THE COURT OF THE C

AND ALL TROWN CONTRACT PRESENTS SHALL COME:

UNITED STATES DEPARTMENT OF COMMERCE
United States Patent and Trademark Office

September 08, 2004

THIS IS TO CERTIFY THAT ANNEXED HERETO IS A TRUE COPY FROM THE RECORDS OF THE UNITED STATES PATENT AND TRADEMARK OFFICE OF THOSE PAPERS OF THE BELOW IDENTIFIED PATENT APPLICATION THAT MET THE REQUIREMENTS TO BE GRANTED A FILING DATE.

APPLICATION NUMBER: 60/491,390

FILING DATE: *July 31, 2003*

RELATED PCT APPLICATION NUMBER: PCT/US04/24365

Certified by



Jon W Dudas

Acting Under Secretary of Commerce for Intellectual Property and Acting Director of the U.S. Patent and Trademark Office

Approved for use through 4/30/2003, OMB 0551-0032 U.S. Petent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Perperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid CMB control number.

PROVISIONAL APPLICATION FOR PATENT COVER SHEET

This is a request for filing a PROVISIONAL APPLICATION FOR PATENT under 37 CFR 1.53(c).

Express Mail Label No. EU364462471US

7698

C

INVENTOR(S)		
Given Name (first and middle [if any])	Family Name or Sumame	Residence (City and either State or Foreign Country)
Edward	Spellman	Grafton, OH
Additional inventors are being named	on theseparately numbered sh	- O1 =
	TITLE OF THE INVENTION (500 characters ma	x) ⊃¥
VEHICLE SEAT MOUNT EQUIPME	NT RACK	607
Direct all correspondence to:	CORRESPONDENCE ADDRES	
X Customer 37053	→	37053
	tomer Number here	PATENT TRADEMARK OFFICE
Firm or Individual Name		
Address		
Address City		
Country	State Telephone	ZIP Fax
	NCLOSED APPLICATION PARTS (check all that	
X Specification Number of Pages Drawing(e) Number of Sheets Application Data Sheet. See 37 CFF	CD(s), Number Cther (specify)	
	FOR THIS PROVISIONAL APPLICATION FOR PA	ATENT
Applicant claims small entity status.	See 37 CFR 1.27,	FILING FEE AMOUNT (\$)
A check or money order is enclosed The Director is hereby authorized to fees or credit any overpayment to D Payment by credit card. Form PTO-	charge filing eposit Account Number:	\$80.00
The Invention was made by an agency of the United States Government: No.	he United States Government or under a contract we need to be a contract when the Government contract number a	
Respectfully submitted.	[Page 1 of 2]	ate 7/31/03
SIGNATURE SIGNATURE		EGISTRATION NO. 47,963
TYPED or PRINTED NAME Dwight A. S	Materian D	ocket Number: ES-101 prv

TELEPHONE (216) 381-6599

USE ONLY FOR FILING A PROVISIONAL APPLICATION FOR PATENT

This collection of information is required by 37 CFR 1.51. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 8 hours to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Cificer, U.S. Patient and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Mail Stop Provisional Application, Commissioner for Patents, P.O. Box 1459, Alexandria, VA 22313-1450.

PROVISIONAL APPLICATION FOR PATENT

SPECIFICATION 14 pages including annotated drawings

Docket

: ES-101 prv

Title

: Vehicle Seat Mount Equipment Rack

Inventor

: Edward Spellman

Agent : Dwight A. Stauffer

The present application comprises copies of lab book notes from the inventor's development of the invention (some copied pages having further annotations according to the inventor), several drawings/sketches produced under the inventor's direction, and additional description according to the inventor (the present document).

The drawings include:

- page labeled (1) = a top view of the rack including transparent views of the hook bars and spring within the tube that is mounted under the shelf,
- page labeled (8) = a detailed drawing of the hook bar (also referred to as a support bar, or end hook),
- page labeled (9) = an overall side view of the rack with an exemplary DVD player in place on the shelf of the rack, and page labeled (10) = alternate embodiment of hook bars in tube (shown as transparent) that press outward against headrest posts, a drawing for an embodiment of the spacer bushing, and a drawing of a hook bar having anti-pivot means engaged with the posts of a headrest (top view).

It should be noted that the notes are chronologically organized and represent potentially different embodiments at different stages of the invention's development, all of which should be considered within the scope of the invention. It may be noted that the page label (1) drawing shows an earlier version of the hook bar, that is improved in the page label (8) drawings of the hook bar, especially with reference to the extension of the inward end, and the safety release design of the hook. The page label (9) and (10) drawings illustrate the most recent embodiment.

Summary of Features of Vehicle Seat Mount Equipment Rack Ed Spellman 7/29/03, edited and expanded 7/30/03

RACK SYSTEM IN GENERAL

- Rack system is used to hold electronic equipment, i.e., portable DVD players, CD
 players, notebook computers, computerized game systems, PDAs, etc., between
 two adjacent adjustable height vehicle headrests (i.e., headrests that are supported
 on at least one round post).
- Rack system is comprised of: a telescoping means with an attached shelf means, and means of holding equipment to the shelf means. Preferred embodiment is a rigid, hollow support tube (square or rectangular), two hook bars sliding within the tube, and a shelf attached to the side of the tube. Alternate embodiments include but are not limited to: hollow hook bars sliding on an internal rod, hook bars with ridges sliding in grooves of an adjacent support bar, hooks at ends of telescoping tubes, etc.
- Rack system could also have a means to load the hook bars against the headrest posts, e.g. via tension spring(s), e.g., via set screw. This will allow rack system to be easily installed in and removed from virtually any vehicle that has 2 adjacent adjustable height headrests. Exemplary alternate embodiment see page label (10) is compression spring means for pushing the hook bars apart, and a notch (e.g., an outward opening Vee) on the end of each hook bar.
- Rack system could also have electrical wiring strain relief clips or other strain relief provisions attached to or built into the support tube and/or shelf.
- Rack system could also have built in compartments or pockets for various items such as: remote controllers, DVDs, patch cords, head phones, etc.
- Rack system could also have accessory items such as: headrest post spacer bushings to help steady the rack when one or both headrests are extended up, and elastic cords that extend between the bottom front of the shelf to the bottom of the seats and/or center console. These accessories will help to stabilize the rack system when transversing rough roads or terrain. The headrest post spacer bushing could be a compressible foam hollow tube with a slit (e.g., longitudinal or

helical) so that it can be easily fitted coaxially onto the headrest post above the hook bar, thereby filling the space between the hook bar and the raised headrest and thus pressing down on the hook bar.

SHELF

- Shelf can have a non-skid texture, coating, laminate, or covering (e.g., rubber mat) to help prevent movement of the mounted equipment.
- Shelf has one or more back stops. Back stops can be moved and repositioned to
 avoid interference with switches, connectors, jacks, etc. that may be on the back
 of the mounted equipment. Back stops can be covered with a resilient material to
 prevent marking of the mounted equipment.
- Equipment is secured to the shelf via easy to remove or unlatch hold-down means including: elastic cord(s), belt(s), clip(s), or suction cup(s), etc.. Ease of equipment installation and removal is important in order to encourage safe storage of equipment when unattended, i.e., theft protection.

SUPPORT TUBE

- Support tube keeps the hook bars in axial alignment, supports the shelf, holds the
 hook bar stop pins, and prevents rotation of the shelf (e.g., tube has rectangular
 cross-section and is close-fitting around rectangular cross-section hook bars).
- Provides means to limit lateral sliding of tube/shelf. Limiting means include, for
 example, set screw, shim spring, indented portion of tube wall, angled tube wall
 and other means to cause friction between tube and at least one of the hook bars.

HOOK BARS

- Hook bars have stop ribs to prevent excessive extension or retraction. These ribs contact the stop pins to limit hook bar travel.
- Hook bars have a extended inner end to provide a bearing surface for adequate rack rigidity when hook bars are fully extended (up to stop pins).
- Hook bars have disengagement means to allow the rack to disengage from the
 headrest posts if the rack is hit from behind with sufficient force. This is a rear
 seat passenger safety feature. Preferred embodiment of hook bar has a ramp-out

D . 0 C1

hook profile and the hook portion of each hook bar opens rearward relative to the vehicle. Preferably there is also anti-pivot means to prevent the rack system from disengaging from only one post and then swinging around the other post to hit a passenger in the front seat. For example, a lanyard could limit such pivoting travel. For example, the hook bar could extend beyond the hook on the near post to rest in front of the far post of the headrest - see drawing on page label (10). Break-apart means could also be incorporated in any of these designs.

- Hook bars have a spring pocket to allow for the use of a longer spring. This allows for a large extension range while keeping the spring stresses low.
- Extension spring is attached to the hook bars via a metal pin, preferably at the
 lateral center (on the central axis) of the hook bar, or at least near the center of the
 pin. This spreads out, and therefore reduces, spring loading on the bar which may
 be plastic. This may be important when the rack is fully extended in a hot
 vehicle.

NOTE: SPECIFICATION CONTINUES ON PHOTOCOPIES OF UNTYPED PAGES WITH SKETCHES AND ONE PROFESSIONAL DRAWING


TOP VIEW book pegs to stop

(TRANSPARENT) bles for speak to stop

(TRANSPARENT) bles for speak to stop

(T

2 hook bars slide in rectange hollow tube, linked by tension spring. Tube is affixed to bottom of rack



page 6/14

Look with hook Fell extended in 7.430"

303-2- 33-(7.43)2 = 18.14 +2(25)

between from lin Stop to Content of Hook when fully returned = .063+.30+.63+.063 = 1.055

Longe of Supports Take = 18.14 + 2(.25)= 12.64"

hook when fully Retreated = 1.055-25= .805

Contre Dataman Between Hooks when Fully Februard = 18.64 + 2(.805) = 20.25"

20.25-18,50 = 1.75" = protected the 1" I was away
so This Suge increases Filly Returbed Contributiones
by 1.75" The is OK.
This New design will have books that extend
From 201/2" To 33" CRATTRE DISTANCE

Distance From Cester of hook to end of Past (ed book) = 9.00 - .25 - . 14 = 8.61"

Dature between 2 ends when Fully Returned = 2012-2(8.61)


allow for home whel April extension to elimiter halles.
Correct Post year Spring is 41/2 home

page 7/14



Can a Sping be foul that has a 3.13' fee lagter that some extend for 15.63" (33-20.53+3.13) with t being overstand ?

TE wat put a blid in the end book Tooking the rake a protect for the Affirm which all a NOV Hole for Spiritetimen them



below from end to Sping retertion Pin = . 12+ . 60+ . 12

men to explorate att ead ale subT end of such Piece

~ Now Spin Longth = 3.13+2(.25)+2(.88)

so Spin much to be able to extend from a Free length H 5.39 To 17.89"

Total exterior = 1789-5.39

Curet Spin estades a Total of 9.0"
Curet Spin a \$ 1.5" land 00 optemen. natur = 9.00 = 2

New Spring mod to extend 12.5" Spen to 5.29" long.

-the should be OK took spend String



Note: Potest "6, 374,040 Dotal agil 16 2002 uns regel and det is set to the place of Letape

6, 330, 377 "antonotive entertainment jupitern for Acar scaled Passangers"

2) "Partolla DVD Planger shalf" ->0
3) "Partolla DVD Planger Casa ">0
4) "Partolla DVD Planger Rock" >0
1.11 0.00 " "00

5) "Partille DVD Player Apport" 0

Claded for ferritured for altering in Clouded 2 100 Listed

والمنظم والمناسبين والمنازي والمناز والمناز والمنازي والم

letel 1

O Listal

ماسئلال

in Orbertin

.188 3) SPR.~ (1)

page 10/14

7/28/03 Spoke To Jule Katilius at Mark Mobiling I described the

Rud hook to him. His Suppertance were:

- ABS (2: 70/14), used in abot of automotive

interior applications

- Alimina Tool is good for 25-30,000 Parts


- Dose in a broll (28 Ton) guess

- Use local wall shop, Clarland has late of the


He surgested of they to reach BERNIE SCHAIB

(214) 397-1246


page 11/14



page 12/14



page 13/14



Document made available under the Patent Cooperation Treaty (PCT)

International application number: PCT/US04/024365

International filing date:

29 July 2004 (29.07.2004)

Document type:

Certified copy of priority document

Document details:

Country/Office: US

Number:

60/491,390

Filing date:

31 July 2003 (31.07.2003)

Date of receipt at the International Bureau:

15 September 2004 (15.09.2004)

Remark:

Priority document submitted or transmitted to the International Bureau in

compliance with Rule 17.1(a) or (b)



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

□ BLACK BORDERS
□ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
□ FADED TEXT OR DRAWING
□ BLURRED OR ILLEGIBLE TEXT OR DRAWING
□ SKEWED/SLANTED IMAGES
□ COLOR OR BLACK AND WHITE PHOTOGRAPHS
□ GRAY SCALE DOCUMENTS
□ LINES OR MARKS ON ORIGINAL DOCUMENT
□ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.